



Software?




<your tool here>








Nagios®




24h: Peak ~1.1G

1W: Peak >600M

1Y: Peak ~250M









disk_free == 0

 $\frac{\text{disk_used}}{\text{disk_available}} > 0.99$

disk_free < 1 GByte

predict_linear(disk_free[1h], 1h) <= 0</pre>





737 Flight Crew Operations Manual

< ENGINE FIRE, SEVERE DAMAGE OR SEPARATION >

Condition: Fire is detected in the related engine; severe damage which may be associated with airframe vibration and/or abnormal engine indications has occurred; or the engine has separated.

AUTOTHROTTLE (if engaged)DISENGAGE
[Allows thrust levers to remain where manually positioned.]
THRUST lever CLOSE [Assists in recognition of the affected engine.]
ENGINE START lever
ENGINE FIRE WARNING switch Pull To manually unlock the engine fire warning switch, press the override and pull.
If the engine fire warning switch or ENG OVERHEAT light remains illuminated:
ENGINE FIRE WARNING switch Rotate L or R Rotate to the stop and hold for one second.
If after 30 seconds the engine fire warning switch or ENG OVERHEAT light remains illuminated:
ENGINE FIRE WARNING switch
Rotate to the opposite stop and hold for one second.

If high airframe vibration occurs and continues after engine is shut down:

Without delay, reduce airspeed and descend to a safe altitude which results in an acceptable vibration level. If high vibration returns and further airspeed reduction and descent are not practicable, increasing airspeed may reduce vibration.

Continued on next page

Copyright © The Boeing Company. See title page for details.

BOEINE

7.17

737 Flight Crew Operations Manual

HIGH ENGINE VIBRATION

Condition: VIB levels are in excess of 4.0 units accompanied by airframe vibrations.

If not in icing conditions:

AUTOTHROTTLE (if engaged) DISENGAGE
[Allows thrust lever to remain where manually positioned.]

Note: If the VIB indication does not decrease when the thrust lever is retarded, check other engine indications. If other engine indications are normal, no further action is needed.



If in icing conditions:

During descent or holding accomplish the following on one engine at a time at approximately 15 minute intervals:


ENGINE START switch FLT

Adjust thrust to 45% N1. After approximately five seconds, advance thrust lever slowly to a minimum of 80% N1.

If vibration does not decrease:

Accomplish the procedure for "If not in icing conditions."









During the Incident

Step back and think

Communicate

Document everything

Collaborate











Postmortems

Reason For Outage

Never Lie to your Customer!

Summary

Before the incident:

- Evaluate every Alarm and its severity
- Write runbooks
- Define communication & collaboration strategy
- Build Dashboards & Logging
- Practice incidents

During the incident:

- Step back and think
- Communicate & Collaborate
- Document every step

After the incident

- Write & review Postmortems
- Write honest RFOs

Further Reading

- https://landing.google.com/sre/
- https://www.fema.gov/national-incident-management-system
- Post Mortems: https://github.com/danluu/post-mortems
- David N. Blank-Edelman's Seeking SRE
- https://www.usenix.org/srecon

